

FIG. 2




FIG. 3




FIG. 4

FIG. 5

OK – no	defect	pass	pass	1	ı	
F5 –	defect	fail	ı	pass	fail	
F4 –	defect	fail	1	pass	pass	
F3 –	defect	fail	1	fail	•	
F1 -	defect	pass	fail	ı	•	
		T1 – test	T2 - test	T3 – test	T4 - test	

FIG. 6

ou	ct		
OK – no	defect	0.5	0.5
F5 –	defect defect	0	
F4 –	defect	0	1
F3 –	defect	1	0
F1 –	defect	0.5	0.5
		T3 – fail	T3 - pass
			r.

FIG. 7